

Figure A-1 The calibration curve of Fe.




Figure A-2 The calibration curve of Mg.




Figure A-3 The calibration curve of Ca.




Figure A-4 The calibration curve of Zn.




Figure A-5 The calibration curve of Pb.




Figure A-6 The calibration curve of Cr.




Figure A-7 The calibration curve of Cd.




Figure A-8 The calibration curve of Cu.




Figure A-9 The calibration curve of Mn.




Figure A-10 The calibration curve of As.




Figure A-11 The calibration curve of Ni.